

Annexure D

BUILDING SAFETY CERTIFICATE

Dated: 22-09-2025

No. 864

It is certified that the existing building **Sri. Sanjeev Public School** (name of the building or premises) at **Lingasugur Taluka : Lingasugur Dist:Raichur.** (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	G+2					

The building is owned/occupied by **Sri. Sanjeev Public School**(name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **Assistant Executive Engineer Public Works Department** (Name of Department/ Govt.) on **22-09-2025** (date of inspection) in the presence of **Pricipal** (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from **22-09-2025** for a period **1 Yeas** in accordance with rule and subject to compliance of the specific conditions as appended.

1. In Future If the building has any issues relating to any cracks, collapse and leakage of water immediate action should taken and you only the responsible
2. Should procure Fire Safety Certificate from Fire Department their recommendations should be followed and updated regularly
3. Original Documents of Building Should kept Safely

Issued on **22-09-2025** at **Lingasugur** by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal : _____

Name : _____

Designation : _____

Name & Address of Department/ Office: _____